Blue**Shaper** PRO®

ZARC

	TAPER	Ø
Z5	6-5%	0,30
Z6	5-4%	0,40
Z7	5-4%	0,50

Blue**Shaper** PRO ®

ZARC

Z1-Z4 Basic sequence
(85% of cases)

Z5-Z7 if necessary
(15% of cases)

KFile
#10

| Z1 | Z2 |

RPM: 500
Torque: 4

| Z3 | Z4 | Z5 | Z6 | Z7 |

RPM: 500
Torque: 4

Irrigate, recapitulate with a 10 file and re-irrigate after removing each rotary file

Glide Path

Shaping

Finishing