

SlimShaper®

ZARC

	MFD	TAPER	Ø
ZS1	0,80	2-6%	15
ZS2	0,80	4-3%	20
ZS3	0,84	4-3%	25

SlimShaper®



KFile
#10

Glide Path



ZS1
RPM: 500
Torque: 3

Shaping



ZS2 **ZS3**
RPM: 500
Torque: 3

Finishing



Irrigate, recapitulate with a 10 file and re-irrigate after removing each rotary file