



ZARC

SlimShaper PRO

TAPER

Ø





SlimShaper PRO



KFile
#10



Glide Path



ZS1
RPM: 500
Torque: 3



Shaping



ZS2 **ZS3**
RPM: 500
Torque: 3



Finishing



Irrigate, recapitulate with a 10 file and re-irrigate after removing each rotary file