

SlimShaper®

ZARC

		TAPER	Ø
ZS1		2-6%	15
ZS2		4-3%	20
ZS3		4-3%	25

SlimShaper®



KFile
#10

Glide Path



ZS1
RPM: 500
Torque: 3

Shaping



ZS2 **ZS3**
RPM: 500
Torque: 3

Finishing



*Irrigate, recapitulate with
a 10 file and re-irrigate
after removing each
rotary file*